

Under Review Notification

Raised By: Scott Cameron

Product #: RBEM632V3009133

Date: Oct 6 2017

Product Name: SEAL HOLDER EXTRACTOR

Part Number (D-Part and 9-Digit) (eg. D3535-11) (eg. D3535-25) (eg. D206-642-143)	Drawing or Document & <u>Current</u> Affected Revision for each part listed	"Y" or "N" Required for Each Part Do not leave blank							Reserved ECN Log Number	Instructions Relevant to Each Part (including whether CHG #'s will be affected)
		HOLD SHIPMENT	Red Tag/Quarantine Stock	Advise Customers	Stop Production	Re-Work Stock	PP Under Review	Product Specifications Under Review ("Bluefiles")		
RBEM632V3009133-1	RBEM632V3009133 Rev 1	Y	N	N	Y	N	Y	N	17-700	Stop production
RBEM632V3009133-3	RBEM632V3009133 Rev 1	Y	N	N	Y	N	Y	N	17-700	Stop production
RBEM632V3009133-5	RBEM632V3009133 Rev 1	Y	N	N	Y	N	Y	N	17-700	Stop production
RBEM632V3009133-7	RBEM632V3009133 Rev 1	Y	N	N	Y	N	Y	N	17-700	Stop production
RBEM632V3009133-13	RBEM632V3009133 Rev 1	Y	N	N	Y	N	Y	N	17-700	Stop production
RBEM632V3009133-15	RBEM632V3009133 Rev 1	Y	N	N	Y	N	Y	N	17-700	Stop production
RBEM632V3009133-17	RBEM632V3009133 Rev 1	Y	N	N	Y	N	Y	N	17-700	Stop production
RBEM632V3009133	RBEM632V3009133 Rev 1	Y	N	N	Y	N	Y	N	17-700	Stop production

Description of Issue:

Rev 1 drawing has functional issues

- Features of OEM tool were omitted (alignment dowel pins on bottom of -9, beside -17 legs)
 - 17 LEGS will not turn freely, interferes with spring plungers -29. Changes to -17 and -13 required
 - 15 is fully threaded, original design is partially threaded
 - 1/-3/-5/-7 were machined from one solid part on OEM part
- Rev B drawing will be released to correct these issues

Distribution:

VP Operations

Director of Operations

Director Quality Assurance

Director of Engineering

Chief Engineer

Engineering Project Managers

Engineering Clerk

Customer Support Manager

Production Engineers

Production Planners

Purchasing Manager

Technical Support

Product Manager - Solutions Provider